

1/31

FIG.1





FIG.2



2/31

FIG.3






FIG.4




3/31

FIG.5



4/31

FIG.6



5/31

FIG.7






FIG.9



6/31

FIG.8



7/31

FIG.10





FIG.11



8/31

FIG.12





FIG.13





9/31

FIG.14





FIG.15



10/31

FIG.16





FIG.17



11/31

FIG.18





FIG.19



12/31

FIG.20





FIG.21



13/31

FIG.22


SAW BLADE  
HOUSING SECTION  
SIDE↑ D  
FAN SIDE

FIG.23



SAW BLADE  
HOUSING SECTION  
SIDE↑ D  
FAN SIDE

FIG.24

SAW BLADE  
HOUSING SECTION  
SIDE↑ D  
FAN SIDE

14/31

FIG.25





FIG.26



15/31

FIG.27




FIG.28




FIG.29





FIG.30





17/31

FIG.31





FIG.32



18/31

FIG.33






FIG.34




19/31

FIG.35



20/31

FIG.36



21/31

FIG.37





FIG.38



22/31

FIG.39





FIG.40



23/31

FIG.41





FIG.42



24/31

FIG.43






FIG.44






25/31

FIG.45



26/31

FIG.46



27/31

FIG.47





FIG.48



28/31

FIG.49





FIG.50



29/31

FIG.51





FIG.52



30/31

FIG.53





FIG.54



31/31

FIG.55

